

M/S Superstar (Tallink)

- Defective wall panels replacement in the cafeteria and bar
- Perfume and distillery shop furniture alternation
- Shop deck covering replacement
- Carpeting replacement in corridors
- Furniture alternation in corridors
- Antislip mounts replacement on the corners of gangways
- Carpeting replacemt near information desk
- Tiles reinstallation in laundry room and change of foundation for washing machines
- Sliding doors A60 coasting replacement

